



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
October 7, 2008

Reviewed PRB

<b>Mine Name:</b> Rhac-Rae	<b>Permit Number:</b> S019/0064
<b>Operator Name:</b> Black Gold Organic Fertilizer	<b>Inspection Date:</b> July 29, 2008
<b>Inspector(s):</b> T Munson	<b>Time:</b> 2:00 PM - 2:30 PM
<b>Other Participants:</b> None	<b>Mine Status:</b> Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 11/16/2010 **Bond Amount:** \$20,700 **Permit fee** delinquent

**Purpose of Inspection:** To verify that the barrels of potentially hazardous waste had been removed from the site based on the issuance of cessation order # MC-2008-25-01.

**Inspection Summary:** The operator contacted me on July 16, 2008 to inform me that the barrels had been removed and I could perform my inspection. I arrived onsite on July 29, 2008 and photo documented that the barrels had been removed. The cessation order can now be terminated.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Operator still has oil and grease on site in an open containment that should be emptied and other oil and grease buckets that exist on site should be put in proper containers so spills do not occur. OGM to continue annual inspections and monitor the site when in the area. A call will be made to the operator to request permit fees.

**Inspector's Signature**

TM:pb

cc: (OPERATOR)

wstokes@utah.gov

O:\M019-Grand\S0190064-RheaRae\inspections\insp-07292008.doc

0006

S0190064 - Black Gold Organic Fertilizer  
Photos taken 07/29/2008



Hazardous waste barrels removed from site



Barrels removed from embankment of pond



Oil waste contained in metal tray. This tray needs to be cleaned before it becomes a problem.



Other bags of materials are found on site and although they are considered nonhazardous they should be stored out of the weather before they become unusable and spill on the ground.